

HEATING HEAD FOR MASSAGE GUN

Battery capacity	900 mAh
Battery type	18350
Charging time	3–3.5 Hours
Applicable charger	5V–2A Mobile phone charger
Output current	0.21-0.23A
Power off protection time	15 Minutes
Maximum temperature	Gear 1: 44°C Max Gear 2: 56°C Max Gear 3: 61°C Max



Press the Power Button once, and the first heating indicator will light up. Press the Power Button a second and third time, and the remaining two heating indicators will light up one by one. To turn off the device, press the Power Button again when all heating indicators are on.

A blue power indicator light suggests that the battery is in normal condition. A flashing red power indicator light suggests that the battery is low and needs to be charged.

The power indicator light is red during charging, and it will turn blue when fully charged.